



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER JOHN R. BAZA
Executive Director Division Director

Inspection Report
Minerals Regulatory Program
August 03, 2010

Reviewed: PRB

Mine Name: Nielson Sandstone	Permit Number: M/023/0012
Operator Name: Ash Grove Cement Company	Inspection Date: August 11, 2010
Inspector(s): Wayne Western	Time: 3:00 pm to 3:20 pm
Other Participants: none	Mine Status: ACT

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Bond Amount:

\$1,332,126.00 escalated until May 8, 2013.

Permit Fees:

Paid for 2009

Inspection Summary:

The site is an active operation. The site was stable, no problems with slope stability were found.

Conclusions and Recommendations:


The Division should continue to monitor the site.

Inspection Date: August 3, 2010
Page 2 of 2
M/023/0012

Directions to Site:

Turn west approximately ½ mile north of mile maker 14.

Inspector's Signature

A handwritten signature in black ink, appearing to read "Wayne Walter", written over a horizontal line.

WHW::pb

cc: Bruce Newell

Jerry_Mansfield@BLM.gov

O:\M023-Juab\M0230012-NielsonSSQuarry\Inspections\Insp_08032010.doc